Getting the Technology

Right: Laying Strong Foundations for the Atmospheric CO₂ Removal Industry

ACTION

Members of Congress should:


- Ensure development of carbon dioxide removal technologies (CDR) is carried out prudently, using only carbon-free energy sources.
- Support NIST in establishing mechanisms and standards for accurate measurement, reporting, and verification for this emerging industry.

What is CDR


Methods and technologies for directly removing carbon dioxide molecules from the air.

Why CDR

To meet specific emissions and climate goals, we might need to implement largescale CDR strategies, even with aggressive efforts to reduce emissions.



Direct Air Capture, a Cyclic CDR Technology




a "once-through" CDR Technology


The Challenges We Must Meet

CDR technologies, even at highest possible efficiencies, require significant resources, either in energy or materials. The energy used for CDR must be carbon-free, and landuse must be balanced with food-production.

Example Resource Requirements for Two Different Families of CDR technologies

Example requirements (in gigawatt-years, GWy) for energy-intensive approaches to remove one gigaton of CO₂





Charting a Path for Sensible Use of CDR Technologies

Along with research to determine effectiveness, economic and policy frameworks for carbon management are needed to facilitate balancing the costs and benefits of large-scale CDR and emission reduction strategies.

- CDR systems must be powered by carbon-free power sources and should not compromise efforts to reduce carbon emissions.
- Reliable systems of measurement, reporting, and verification (MRV) need to be developed for CDR systems. Robust standards for sequestration and for safety and environmental impact are also needed.

The American Physical Society is a nonprofit membership organization working to advance and diffuse the knowledge of physics through its outstanding research journals, scientific meetings, and education, outreach, advocacy, and international activities. APS represents over 50,000 members, including physicists in academia, national laboratories, and industry in the United States and throughout the world. APS Government Affairs | selton@aps.org | (202) 846-8125 | cvd.aps.org

